

Clarke®



PRODUCTION WORKBENCH WITH DRAWER

MODEL NO: CWB2001P
PART NO: 7637809

ASSEMBLY INSTRUCTIONS

SPECIFICATIONS

	CWB2001P
Dimensions (w x d x h) mm	2000 x 650 x 865
Weight	68 kg
Maximum Load (table top)	300 kg
Maximum Load in Drawer	30 kg
Maximum Load (shelf)	80 kg
Maximum Load (CD3WB 3- drawer unit-sold separately)	90 kg

SAFETY PRECAUTIONS

ALWAYS seek assistance when lifting heavy items.

ALWAYS keep children and animals away from tools and work areas.

ALWAYS keep work area clean and free from oil spills etc.

ALWAYS wear protective footwear when assembling the workbench.


ASSEMBLY

Thank you for purchasing this CLARKE product. Please read and follow the instructions carefully. Unpack your workbench and check to ensure that no damage was suffered during transit. Should any damage be apparent you should contact your CLARKE dealer immediately.

The kit comprises the workbench top, lower tray and four legs with 16xM8 bolts with nuts and flat washers, the drawer, backstops and drawer runners with M6 screws. Position multiple units to create a run of benches for industrial use.


The workbench is best assembled with the help of an assistant.

1. Rest the workbench top upside down on a soft, protective surface and fit the drawer backstops to the base using the 4 x M6 screws, washers and bolts. Use with a CD3WB 3-drawer unit only.
2. At each of the rear mountings, attach a leg, with the foot pad




downwards using two M8 bolts with each leg, ensuring a flat washer is used with the nut. Nip up the nuts - DO NOT fully tighten.


3. Attach the front legs in a similar manner using M8 bolts with nuts and flat washers. DO NOT fully tighten.




4. With the help of an assistant, position the shelf between the legs, and bolt it to the legs using M8 bolts with nuts and flat washers. DO NOT fully tighten the nuts.
 - NOTE The tray has an upstand at the back only.



5. Turn the workbench on to its feet and shake it vigorously to ensure it is completely stable and resting evenly on all four legs, then fully tighten all nuts.
6. Fit the drawer runners to their locations on the workbench frame by engaging the tabs with the slots.



7. Slot the drawer into place in the runners.
8. If a CD3WB 3-drawer unit is purchased, this can be slotted into place on the spare runners.



A SELECTION FROM THE VAST RANGE OF

Clarke®

QUALITY PRODUCTS



AIR COMPRESSORS

From DIY to industrial, Plus air tools, spray guns and accessories.

GENERATORS

Prime duty or emergency standby for business, home and leisure.

POWER WASHERS

Hot and cold, electric and engine driven - we have what you need

WELDERS

Mig, Arc, Tig and Spot. From DIY to auto/industrial.

METALWORKING

Drills, grinders and saws for DIY and professional use.

WOODWORKING

Saws, sanders, lathes, mortisers and dust extraction.

HYDRAULICS

Cranes, body repair kits, transmission jacks for all types of workshop use.

WATER PUMPS

Submersible, electric and engine driven for DIY, agriculture and industry.

POWER TOOLS

Angle grinders, cordless drill sets, saws and sanders.

STARTERS/CHARGERS

All sizes for car and commercial use.



This product is guaranteed against faulty manufacture for a period of 12 months from the date of purchase. Please keep your receipt which will be required as proof of purchase.

This guarantee is invalid if the product is found to have been abused or tampered with in any way, or not used for the purpose for which it was intended. Faulty goods should be returned to their place of purchase, no product can be returned without prior permission.

This guarantee does not affect you statutory rights.

PARTS & SERVICE: 020 8988 7400

E-mail: Parts@clarkeinternational.com or Service@clarkeinternational.com

SALES: UK 01992 565333 or Export 00 44 (0)1992 565335

Clarke® INTERNATIONAL, Hemnall Street, Epping, Essex CM16 4LG
www.clarkeinternational.com