

3PC WIRE BRUSH SET

Model No: CHT561 Part No: 1801561

IMPORTANT

NEVER exceed the maximum running speed (4,500rpm).

GENERAL SAFETY PRECAUTIONS

NEVER apply excess pressure, ALWAYS allow the tool to do the work ALWAYS inspect the brush for defects/damage before using, if in doubt DO

ALWAYS ensure the drill is switched OFF and isolated from the main electrica

ALWAYS ensure the affilis switched OFF and isolated from the main electrical supply before fitting/removing brushes.

ALWAYS ensure the brush is firmly secured before switching ON.

ALWAYS wear safety goggles, manufactured to the latest European Safety Standards. Everyday eyeglasses do not have impact resistant lenses, they are not safety glasses.

ALWAYS use a face or dust mask if operation is particularly dusty

ALWAYS keep children away. All visitors should be kept a safe distance from the work area, especially whilst working with tools, in particular power

ALWAYS concentrate on the job in hand, no matter how trivial it may seem Be aware that accidents are caused by carelessness due to familiarity.



Model No: CHT561 Part No: 1801561

IMPORTANT

NEVER exceed the maximum running speed (4,500rpm)

GENERAL SAFETY PRECAUTIONS

NEVER apply excess pressure, **ALWAYS** allow the tool to do the work. **ALWAYS** inspect the brush for defects/damage before using, if in doubt **DO NOT** use

ALWAYS ensure the drill is switched OFF and isolated from the main electrical supply before fitting/removing brushes.

ALWAYS ensure the brush is firmly secured before switching ON.

ALWAYS wear safety goggles, manufactured to the latest European Safety Standards. Everyday eyeglasses do not have impact resistant lenses, they not safety glasses.

ALWAYS use a face or dust mask if operation is particularly dusty

ALWAYS keep children away. All visitors should be kept a safe distance from the work area, especially whilst working with tools, in particular power

ALWAYS concentrate on the job in hand, no matter how trivial it may seem Be aware that accidents are caused by carelessness due to familiarity.



3PC WIRE BRUSH SET

Model No: CHT56 Part No: 1801561

IMPORTANT

NEVER exceed the maximum running speed (4,500rpm).

GENERAL SAFETY PRECAUTIONS

NEVER apply excess pressure, **ALWAYS** allow the tool to do the work ALWAYS inspect the brush for defects/damage before using, if in doubt DO

NOT use.
ALWAYS ensure the drill is switched OFF and isolated from the main electrica supply before fitting/removing brushes.

ALWAYS ensure the brush is firmly secured before switching ON.

ALWAYS wear safety goggles, manufactured to the latest European Safety

Standards. Everyday eyeglasses do not have impact resistant lenses, they are not safety glasses.

ALWAYS use a face or dust mask if operation is particularly dusty

ALWAYS keep children away. All visitors should be kept a safe distance from the work area, especially whilst working with tools, in particular power

ALWAYS concentrate on the job in hand, no matter how trivial it may seem Be aware that accidents are caused by carelessness due to familiarity



3PC WIRE BRUSH SET

Model No: CHT56 Part No: 1801561

IMPORTANT

NEVER exceed the maximum running speed (4,500rpm).

GENERAL SAFETY PRECAUTIONS

NEVER apply excess pressure, ALWAYS allow the tool to do the work. ALWAYS inspect the brush for defects/damage before using, if in doubt DO

NOT use.
ALWAYS ensure the drill is switched OFF and isolated from the main electrical supply before fitting/removing brushes

ALWAYS ensure the brush is firmly secured before switching ON.

ALWAYS wear safety goggles, manufactured to the latest European Safety Standards. Everyday eyeglasses do not have impact resistant lenses, they are not safety glasses.

ALWAYS use a face or dust mask if operation is particularly dusty

ALWAYS keep children away. All visitors should be kept a safe distance from the work area, especially whilst working with tools, in particular pow

ALWAYS concentrate on the job in hand, no matter how trivial it may seem Be aware that accidents are caused by carelessness due to familiarity



3PC WIRE BRUSH SET

Model No: CHT561 Part No: 1801561

IMPORTANT

NEVER exceed the maximum running speed (4,500rpm).

GENERAL SAFETY PRECAUTIONS

NEVER apply excess pressure, ALWAYS allow the tool to do the work.
ALWAYS inspect the brush for defects/damage before using, if in doubt DO NOT use.

ALWAYS ensure the drill is switched OFF and isolated from the main electrica

supply before fitting/removing brushes.

ALWAYS ensure the brush is firmly secured before switching ON

ALWAYS wear safety goggles, manufactured to the latest European Safety Standards. Everyday eyeglasses do not have impact resistant lenses, they

are not safety glasses.

ALWAYS use a face or dust mask if operation is particularly dusty

ALWAYS keep children away. All visitors should be kept a safe distance from the work area, especially whilst working with tools, in particular power

ALWAYS concentrate on the job in hand, no matter how trivial it may seem Be aware that accidents are caused by carelessness due to familiarity.



3PC WIRE BRUSH SET

Model No: CHT561 Part No: 1801561

IMPORTANT

NEVER exceed the maximum running speed (4,500rpm).

GENERAL SAFETY PRECAUTIONS

NEVER apply excess pressure, ALWAYS allow the tool to do the work ALWAYS inspect the brush for defects/damage before using, if in doubt DO

ALWAYS ensure the drill is switched OFF and isolated from the main electrical

supply before fifthing/removing brushes.

ALWAYS ensure the brush is firmly secured before switching ON.

ALWAYS wear safety goggles, manufactured to the latest European Safety Standards. Everyday eyeglasses do not have impact resistant lenses, they are not safety glasses.

ALWAYS use a face or dust mask if operation is particularly dusty.

ALWAYS keep children away. All visitors should be kept a safe distance from the work area, especially whilst working with tools, in particular power

ALWAYS concentrate on the job in hand, no matter how trivial it may seem. Be aware that accidents are caused by carelessness due to familiarity.